



Figure 1: View of the area where the earthen dam failed



Figure 2: View of the former pond area Note: view is looking down stream towards the area where the earthen dam failed



Figure 3: Area where the earthen dam failed



Figure 4: Another view of the dam failure area



Figure 5: View looking immediately downstream from the dam failure area



Figure 6: Sediment deposited in the stream channel just downstream of the dam



Figure 7: Sediment deposited further downstream



Figure 8: Sediment deposited still further downstream



Figure 9: Sediment deposited even further downstream



Figure 10: Culverts which washed down stream from the dam failure area



Figure 11: Sediment deposited still further downstream



Figure 12: Sediment deposited approximately 1/4 mile downstream from the dam failure area

Figure 13:

Figure 14:

Figure 15

Figure 16:

Figure 17:

Figure 18: